

28790

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 497 Survey held at London Date Novr 15th to 21st 1867
 on the Ship "Stonehouse" Master J. Pley
 Tonnage 1153 Built at Pallion When built 1866 (P. No.)
 By whom built Smaythwait Owners J. Morrison
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green's Y^d dry Dock and East India St^k

Last Survey, No. 8858 Port Sunderland Classed B. A. 1 (10.66)

REPAIRS Now done

The Yellow Metal renailed &c; only about two thirds of the bottom seen, there being water in the Dock.

Hold lumbered with cargo, and ballast.

Present Condition of the

Decks	<i>good</i> <i>where</i> <i>seen</i>	Treenails	<i>good</i> <i>where</i> <i>seen</i>	Windlass and Capstan	<i>good</i> <i>and</i> <i>sufficient</i> <i>where</i> <i>seen</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper and J. M.		Standing & Running Rigging	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <i>good where seen</i>				

As far as could be seen she is now in good and efficient condition, and fit in my opinion to remain as Classed, viz A. 1.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 26th November 1867

Character assigned B. A. 1