

REPORT of SURVEY for REPAIRS.

28802

No. in Reg. Book. **No.** 579 Survey held at London Date 28th November 18 67
 on the Ship "Burton Stather" Master Charles Warren
 Tonnage 421 Built at Burton Stather When built 1866 (1. Mo.)
 By whom built Dray Owners Bullard & Co.
 Port belonging to London Destined Voyage Natal
 If Surveyed Afloat or in Dry Dock New frame dock and London Dock.

Last Survey, No. 3635 Port Hull Classed G. A. 1.
3/66.

REPAIRS

Now done:- The Bottom sighted and the Yellow Metal sheathing patched. - Pieced two planks of the Bottom on the starboard - said to have been chafed by the anchor.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where seen.</u>	Breasthooks and Stemson	Pumps <u>Two</u> } <u>Good where seen</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>Three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Good.</u>	Ditto Ditto at other places	Condition, how ascertained <u>By inquiry of Captain.</u>
Planksheers	Keelsons	Sails
Sheerstrakes } <u>Good where seen.</u>	Clamps and Shelves	Anchors No. of <u>15. 2K</u> } <u>Good and</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>16. 15. 2K</u> When put on <u>1866.</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>	

She is now in good and efficient condition, and fit, in my opinion, to remain classed: A. 1.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 3rd December 18 67

Character assigned G. A. 1. m.s.



© 2021

Lloyd's Register Foundation

LON652-0460