

28828

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 206 Survey held at London Date 6th Dec^r 10th 12 1867
 on the Ship Ornate Master E. G. P. March
 Tonnage 738 Built at Harwich When built 1865
 By whom built Vaux Owners J. Morison
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock King & Queen dry dock &

Last Survey, No. 27959 Port London Classed 10. A. 1.
86

REPAIRS

Stripped off the Yellow metal sheathing
 Unwed a bolt or two in the hanging knees
 to deck beams with Yellow metal, - one also in a Hook
 Caulked from Keel to Gunwale, tested the caulking
 at various parts, took the lining off the head of
 tudder, and examined it, examined windlap and put it in order.
 Resheathed with Yellow metal on felt up
 to 19 ft

Present Condition of the

Decks	<u>in good order</u>	Treenails	<u>where seen good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	<u>firm</u>	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<u>from the deck</u>
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	<u>3</u>
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	<u>efficient</u>	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>Felt & gmt</u> When put on <u>Now</u>	Standing & Running Rigging	"
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where tested.</u>				

I am of opinion she is entitled to remain as class'd 10. A. 1.
 Samuel Preshov.

The Amount of Fee.....£ — : — : is received by me.
 Special..... 2 : 2 : } MC
 Certificate (if required) : 5 :

Committee's Minute 17th December 1867
 Character assigned 10 A. 1.



