

REPORT of SURVEY for REPAIRS.

28889

No. in Reg. Book. **No.** 771 Survey held at London Date 29th Nov^r 69 to 4 Jan^y 1868
 on the Ship "Essex" Master Ridges
 Tonnage 1042 Built at London When built 1862 (7 mo.)
 By whom built Wigram Owners Wigram and Sons
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Blackwall dry Dock and East-India Dock

Last Survey, No. 28217 Port London Classed B. A. 1. (H. 6%)

REPAIRS Now done.

Sighted bottom, the Yellow metal patched; the timbers lifted from the main hatch forward, Keelson and floor Jo examined, the remainder of the Hold considerably lumbered with tanks, and dunnage, &c.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>6</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>in opⁿ and enquiry</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. S. 20</u>
Topsides	Ceiling	Cables
Wales	Rudder <u>Ha good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Y.M.</u> When put on <u>1866</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

good where seen

She is now in good and efficient condition, and fit in my opinion to remain as Classed B. A. 1.

The Amount of Fee.....£ : : is received by me, Joseph Keew.

Special.....

Certificate (if required) : :

Committee's Minute 14th January 1868

Character assigned 13A / 9ms