

28899

Rev 16.1.68

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 392 Survey held at London Date Jan 7 - 10th 1868
on the Ship "Marshal Pelissier" Master W. G. Pearne
Tonnage 612 Built at Sunderland When built 1855
By whom built _____ Owners Blyths
Port belonging to London Destined Voyage Mauritius
If Surveyed Afloat or in Dry Dock Union Dry Dock & West India Dock

Last Survey, No. 28130 Port London Classed 10 A. I.
REPAIRS now done, the bottom sighted and the Yellow
metal patched - Cost 65- 3/4

Present Condition of the

Decks	} <u>good</u>	Treenails	<u>good</u>	Windlass and Capstan	
Waterways		Breasthooks and Stemson	<u>not seen</u>	Pumps	} <u>good</u> <u>where</u>
Omings		Transoms, Pointers, and Crutches	<u>not seen</u>	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	<u>seen</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places	<u>where</u>	Condition, how ascertained	<u>by inquiry</u>
Planksheers	} <u>where</u>	Keelsons	<u>greater part not seen</u>	Sails	} <u>good</u>
Deerstrakes		Clamps and Shelves		Anchors	
Upsides		Ceiling	<u>the hold much lumbered</u>	Cables	<u>and</u>
Sides		Rudder		Hawsers and Warps	} <u>Sufficient</u>
Hulk (Bottom) and Counter		Copper	<u>T. L. Y. M.</u> When put on <u>1866</u>	Standing & Running Rigging	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

She is now where seen in good condition
fit in my opinion to remain as classed

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 17th January 1868

Character assigned Cont^d 3/21 was



© 2021

Lloyd's Register Foundation

LN652-0535