

28953

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 357 Survey held at London Date 5. Oct 10th 1867
on the Ship "Dunphail Castle" Master W. Fleck
Tonnage 720 Built at Sunderland When built 1861
By whom built Laing Owners J. Allan
Port belonging to London Destined Voyage Madras
If Surveyed Afloat or in Dry Dock Limerick Dry Dock & East India Dock

Last Survey, No. 27417 Port London Classed 13 A.1
REPAIRS now done,

The bottom caulked and resheathed with Yellow metal upon felt; new step to foremast of Iron bark, and new cheeks and brestle-trees to foremast, the main topmast new and the rigging stripped and overhauled ~

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	good	Breasthooks and Stenson	good	Pumps	good
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	where	Timbers of the Frame at the openings	where	Masts, Yards, &c.	where
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained by inquiry & inspection	
Planksheers	seen	Keelsons	seen	Sails	seen
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B 1 S 2 K</u>	
Topsides	seen	Ceiling	seen	Cables	seen
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>F & Y M</u> When put on <u>now</u>		Standing & Running Rigging	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested -
She is now where seen in good and efficient condition, fit in my opinion to remain as
Classed 13 A.1.

The Amount of Fee.....£ : - : is received by me,
Testing caulking -
Special..... 1 : 1 : SLP
Certificate (if required) : :

Committee's Minute 11th February 18 68
Character assigned 13 A.1
record M was

J. H. Cornish
© 2019
Lloyd's Register Foundation
LON 653-0030