

28957

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 86 Survey held at London Date 7<sup>th</sup> February 18 68.  
on the Barque "Verulam" Master M. Freck  
Tonnage 312 Built at Burton Stather When built 1855 (3. Mo.)  
By whom built Wray Owners Bullard & Co.  
Port belonging to London Destined Voyage Natal.  
If Surveyed Afloat or in Dry Dock. Gun dry dock and London dock.

Last Survey, No. 28087 Port London Classified 11. A. 1.  
2. 67.

## REPAIRS

Now done:- The Yellow metal sheathing stripped off the Bottom, and caulked from Keel to the Gunwale. Renewed the lower piece of Stem, in consequence of the original piece having a rent in it, which caused a leak; the new piece is of English oak. Resheathed the Bottom with Yellow metal on felt.

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>3</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>By enquiry &amp; observation</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 15. 2 K.</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Pl. Gal.</u> When put on <u>Now</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where tested</u>	

She is now in good and efficient condition, and fit, in my opinion, to remain classed: A. 1.

Williamson.

The Amount of Fee.....£ 1 : - : is received by me,  
Special. 1 : 1 :  
Certificate (if required) - : - : W. M. W. A. S.

Committee's Minute 14 February 1868

Character assigned 11  
record Y. M. W. A. S.