

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 145 Survey held at London Date Nov 21st 1867
 on the Brigantine "Aereon" Master Brown
 Tonnage 190 Built at Prince E^d Island When built 1865
 By whom built _____ Owners H. Wright
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 28221 Port London Classed H.F. 1

REPAIRS

How done, the Chain Cables, changed, examined, and found good and sufficient - the Windlass renewed with Sauty's Cast -

Present Condition of the

Decks	Treenails	Windlass and Capstan <u>new</u>
Waterways } <u>Good where</u>	Breasthooks and Stemson	Pumps } <u>Good & sufft</u>
Comings } <u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>Good where seen</u>
Lower Deck Beams & Fastenings } <u>firm</u>	Ditto Ditto at other places	Condition, how ascertained by <u>enging</u>
Planksheers	Keelsons	Sails
Sheerstrakes } <u>Good where</u>	Clamps and Shelves } <u>seen</u>	Anchors No. of
Topsides } <u>seen</u>	Ceiling	Cables } <u>Good and sufft</u>
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	<u>Copper</u> When put on <u>1866</u>	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

She is in good and efficient condition, fit in my opinion to remain classed H.F. 1.

B. T. Wainwright

The Amount of Fee.....£ 10 : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 21st February 1868

Character assigned H.F. 1 was



© 2019

Lloyd's Register
Foundation

LON653-0056