

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date 14<sup>th</sup> April 1868  
 on the Bt Ballarat Master J. Allan  
 Tonnage 685 Built at Merdeen When built 1852  
 By whom built \_\_\_\_\_ Owners Tanner and Co  
 Port belonging to London Destined Voyage Nelson  
 Surveyed Afloat West India and St Katharine's Dock.

Last Survey, No. 28256 Port London Classed 12. A. 1. (4.6%)  
 PAIRS None done. Cont 64. 8 yrs.

Renewed two shifts of Deck on the Port side.

Greater part of Hold lumbered with ballast Sec.

Renewed the Fore-topmast, and Fore Yard, with Red-pine.

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>insp<sup>n</sup> and engin<sup>g</sup></u>
Planksheers	Keelsons <u>not seen</u>	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. W. 11</u>
Topsides	Ceiling <u>part seen</u>	Cables
Wales	Rudder <u>as good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Y.M.C. 2</u> When put on <u>1864</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>	

She is now in good and efficient condition and fit in our opinion to remain as classed 12. A. 1.

The Amount of Fee.....£..... is received by me Joseph Allan.  
 Special.....1-1-0  
 Certificate (if required) 5 Samuel Pursons

Committee's Minute 21<sup>st</sup> April 1868  
 Character assigned Cont 8 E 1 QMAS



© 2019

Lloyd's Register Foundation

LON 653-0149