

# Half Time Survey

## REPORT of SURVEY for REPAIRS.

29117

No. in Reg. Book. **No.** 430 Survey held at London Date July 24 to Aug 7 1867  
 on the BK "Prince Alfred" Master a. aitch  
 Tonnage 258 Built at Aberdeen When built 1862  
 By whom built Duthie Owners J. I. Rennie  
 Port belonging to Aberdeen Destined Voyage Natal  
 If Surveyed Afloat or in Dry Dock Duke Shore Dry Dock & St Katharines Dr  
 Last Survey, No. 27406 Port London Classed 9A.1.  
 4, 66

REPAIRS  
 Now done, The middle line and peaks cleared, the limbers lifted and the windlass unhung and stripped -  
 faulked from keel to gunwale and the bottom re-sheathed with Yellow Metal upon Felt -  
 The waterways and plank sheer caulked -

### Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways <u>caulked</u>	} <u>good</u>	Breasthooks and Stenson	} <u>good</u>	Pumps	} <u>good</u>
Comings		Transoms, Pointers, and Crutches		Boats <u>three</u>	
Upper Deck Beams & Fastenings	} <u>where</u>	Timbers of the Frame at the openings	} <u>where</u>	Masts, Yards, &c.	} <u>where</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Plank sheers <u>caulked</u>		Keelsons		<u>from the deck</u>	
Sheerstrakes <u>do</u>		Clamps and Shelves		Sails	
Topsides <u>do</u>	} <u>seen</u>	Ceiling	} <u>seen</u>	Anchors No. of <u>3B. 1S 2K</u>	} <u>seen</u>
Vales <u>do</u>		Rudder		Cables	
Plank (Bottom) and Counter <u>caulked</u>		Copper <u>F.K. Y.M.</u> When put on <u>now</u>		Hawsers and Warps	
				Standing & Running Rigging	

### General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good condition, fit in our opinion to remain as classed 9A.1.

The Amount of Fee.....£ 1 : 1 : is received by me,

Special..... 1 : 1 :  
 Certificate (if required) -----

Committee's Minute 24<sup>th</sup> April 1868

Character assigned 9A.1  
record G.M. Mas



Lloyd's Register  
 Foundation

LON653-0161