

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 261 Survey held at London Date June 10th to 13th 1868
 on the Ship "Simara" Master R. Langlands
 Tonnage 883 Built at New Brunswick When built 1865 (1 mo.)
 By whom built Nevins Owners Potter and Co
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock King and Queen dry Dock

Last Survey, No. 4934 Port Greenock Classed T.A.1 (6.65.)
 REPAIRS Now done.

Sighted bottom, the yellow metal stripped, Caulked from keel to the metal line, and resheathed the bottom with yellow metal on felt,

A large amount of ballast ice in the hold at the fore and after ends of the ship, and the keelson boxed up with salt.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2 Main & 2 Bilge</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>inspⁿ and enquiry</u>
Planksheers	Keelsons <u>not seen</u>	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 10. 2 M.</u>
Topsides	Ceiling <u>part seen</u>	Cables
Wales	Rudder <u>Ad good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>and Y.M. When put on</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

As far as could be seen, she is now in good and efficient condition, and fit in my opinion to remain as classed. T.A.1.

The Amount of Fee.....£ : : is received by me.

Special...../ . / : 0

Certificate (if required) : 5 :

Committee's Minute 5th May 18 68

Character assigned 7th May
record Y.M. WAS



© 2019

Lloyd's Register Foundation

LN653-0184