

REPORT of SURVEY for REPAIRS.

29390

No. in Reg. Book. **No.** 423 Survey held at London Date May 28th to 9th July 1868
 on the Ship "Shannon" Master J. Watson
 Tonnage 1292 built at London When built 1862 (5 mo)
 By whom built Green Owners R and H Green
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greenes Up^r dry Dock, and East India St^r
 Last Survey, No. 28496 Port London Classed B. A. 1 (D. 6%)
 REPAIRS None done.

Sighted bottom, the yellow metal stripped, caulked from keel to plank sheers, the poop and fore-castle drifts, also the waterway seams in each case, and resheathed the bottom with yellow metal on felt.

Renewed the following viz. Gibbom, Fore-top Gallant, and Fore Royal Yards, with Red pine.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>6</u>
Upper Deck Beams & Fastenings <u>Iron</u>	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>Iron</u>	Ditto Ditto at other places	Condition, how ascertained
Plank sheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. <u>2 B & 2 S</u>
Topsides	Ceiling	Cables
Wales	Rudder <u>Ha good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Sp. Y. M.</u> When put on <u>1868</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

Good and efficient where tested

She is now in good and efficient condition and fit in my opinion to remain as Classed viz A. 1. Her upper and lower deck beams are of Iron, and are not noted as such in the Register Book.

The Amount of Fee.....£ - : - is received by me, Joseph New.
 Special.....1-1-0
 Certificate (if required) : 5 :

Committee's Minute 18th August 1868
 Character assigned 13th Aug



© 2019

Lloyd's Register Foundation
 LON653-0363