

# REPORT of SURVEY for REPAIRS.

29439

No. in Reg. Book. **No.** 706 Survey held at London Date Sept 11<sup>th</sup> 18 68  
 on the 138 "Matilda" Master Ridland  
 Tonnage 239 built at Bristol When built 1850  
 By whom built ✓ Owners Scrutton Son & Co  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock in Union & West India Docks

Last Survey, No. 29048 Port London Classed 12 A1  
 REPAIRS Cont 62.8 gns 3.68

Stripped Yellow metal sheathing, caulked from keel to metal line and re-sheathed with Yellow metal over felt.

Drove out many iron bolts in range of lower deck beams and substituted others of Yellow metal, also added many yellow metal dumps in butts of outside planking.

Was surveyed for half time in Dec<sup>r</sup> 1865

## Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>" " "</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>" " "</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>" " "</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Condition, how ascertained <u>from enquiry &amp; as seen from deck</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Sails <u>" " "</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>" " "</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Cables <u>" " "</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Hawsers and Warps <u>" " "</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>F&amp;YM</u> When put on <u>1868</u>	Standing & Running Rigging <u>" " "</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 8<sup>th</sup> September 18 68

Character assigned Port 8 B

record B. M. W. 1868



© 2019

Lloyd's Register  
 Foundation  
 LON653-0396



Mattida



© 2019

Lloyd's Register  
Foundation