

REPORT of SURVEY for REPAIRS.

29459

No. in Reg. Book. **No.** 87 Survey held at London Date Sep 27th 12th 1868
 on the Ship "Harkaway" Master Forster
 Tonnage 830 built at Dundee When built 1852
 By whom built _____ Owners Merchant Shipping Co
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock anul Dry Dock & East India Dr

Last Survey, No. 28506 Port London Classed 15 A. 1
 REPAIRS font. 67. 5 3/4

now done,

Bottom sighted, and yellow metal sheathing painted with Peacock's Patent and the Upper Deck faulted —

Present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto Ditto at other places	} <u>well</u>	Condition, how ascertained <u>by inspection & inquiry</u>	} <u>good</u>
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors <u>No. of 3 B 15 20</u>	
Topsides		Ceiling		Cables	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Hawsers and Warps	} <u>good</u>
Plank (Bottom) and Counter		Copper <u>T. & Y. M.</u> When put on <u>1867</u>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<u>good where seen</u>	

She is now where seen in good and efficient condition, fit in my opinion to remain as classed A. 1.

The Amount of Fee.....£ _____ is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 15th September 1868

Character assigned out 5 A. 1



© 2019

Lloyd's Register Foundation