

29549

REPORT of SURVEY for REPAIRS.

No. 2290 Survey held at London Date Feb 17 to Mar 4 1868
on the Ship "Wimmera" Master J. L. Cooper
Tonnage 1008 Built at Aberdeen When built 1866, 5 mo
By whom built Smith Owners Potter & Co.
Port belonging to Glasgow Destined Voyage Port Phillip
If Surveyed Afloat or in Dry Dock Watcliff Dry Dock & East India Dock
Last Survey, No. 2290 Port Aberdeen Classed 7.A.1
REPAIRS 6.66

Now done,

caulked from keel to gunwale,
and the bottom resheathed with Yellow
Metal upon Felt

Present Condition of the

Decks		Treenails		Windlass and Capstan	good
Waterways	good	Breasthooks and Stemson	good	Pumps	&
Comings		Transoms, Pointers, and Crutches		Boats	five
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	sufficient
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where	Condition, how ascertained	by inspection
Planksheers	caulked	Keelsons		Sails	good
Sheerstrakes	"	Clamps and Shelves		Anchors	No. of 3 B. 1 S 2 K
Topsides	"	Ceiling	seen	Cables	and
Wales	"	Rudder		Hawsers and Warps	efficient
Plank (Bottom) and Counter	caulked	Copper	FLM When put on now	Standing & Running Rigging	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good and efficient
condition, fit in my opinion to remain
as classed 7.A.1.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 20/10/68

Certificate (if required) : :

Committee's Minute 23rd October 1868

Character assigned 7.A.1



© 2019

Lloyd's Register
Foundation

LONG53-0474