

REPORT of SURVEY for REPAIRS.

29642

No. in Reg. Book. **No.** 452 Survey held at London Date Nov 19th 1868
 on the S. John R. Worcester Master Thos. Cause
 Tonnage 144 Built at Port Glasgow When built 1865
 By whom built Owners J Patton &
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock & E. S. Dock

Last Survey, No. 28783 Port London Classed 12 A 1

REPAIRS

yellow metal sheathing repaired -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>JM</u> When put on <u>1867</u>	Standing & Running Rigging

General Observations and Opinion, good Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in a good and efficient state of repair and is eligible in my opinion to remain as classed 12 A 1

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 :

Certificate (if required) : 5 :

Thos. J. Wain

Committee's Minute 1st December 1868

Character assigned 12 A 1



© 2019

Lloyd's Register Foundation

LON653-0567