

REPORT of SURVEY for REPAIRS.

29683

No. in Reg. Book. **No.** 160 Survey held at London Date Oct 19 to 22nd 1868
 on the Ship "Farnatic" Master J. Rhind
 Tonnage 871 built at Sunderland When built 1867
 By whom built Pile Owners J & J. Wait
 Port belonging to N. Shields Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock anal Dry Dock

Last Survey, No. 28804 Port London Classed 16 A.1
 1, 68

REPAIRS

now done,

caulked from keel to gunwale
 and the bottom resheathed with yellow metal
 upon felt - fleamed and painted in the
 hold -

Present Condition of the

Decks	good	Greenails	metal bolts	Windlass and Capstan	good
Waterways	where	Breasthooks and Stemson	good	Pumps	and
Comings	seen	Transoms, Pointers, and Crutches	good	Boats	efficient
Upper Deck Beams & Fastenings	seen	Timbers of the Frame at the openings	where	Masts, Yards, &c.	efficient
Lower Deck Beams & Fastenings	seen	Ditto Ditto at other places	where	Condition, how ascertained	by inspection of the deck
Planksheers	caulked	Keelsons	seen	Sails	good
Sheerstrakes	do	Clamps and Shelves	seen	Anchors No. of	and
Topsides	do	Ceiling	seen	Cables	efficient
Wales	do	Rudder	seen	Hawsers and Warps	efficient
Plank (Bottom) and Counter	caulked	Copper	T. L. Y. M. When put on now	Standing & Running Rigging	efficient

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good and efficient condition,
 fit in my opinion to remain as classed 16 A.1.

The Amount of Fee.....£ is received by me,

Special..... 1 : 1 : 18/12/68

Certificate (if required)

Committee's Minute 22nd December 1868

Character assigned 16 A.1

record M. W. A.



© 2019

Lloyd's Register
 Foundation

LONG54-0012