

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 290 Survey held at London Date Jan^y 9th 18 69
 on the "B^e Scotland" Master B^r Brightman
 Tonnage 375 Built at Sunderland When built 1865 5 mo
 By whom built _____ Owners Brightman &
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock St Katharines dock

Last Survey, No. 29722 Port London Classed G A 1
 REPAIRS 65

*This vessel was remetalled and caulked in the
 Globe dry dock.*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Good &</u>
Planksheers <u>where seen</u>	Keelsons <u>where seen</u>	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>sufficient</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>T. & W.</u> When put on <u>now</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen</u>	

*This vessel is now in good order
 and eligible in my opinion to remain
 as classed G A 1*

The Amount of Fee.....£ _____ is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 12th January 18 69

Character assigned G A 1

record M 1122



© 2019

Lloyd's Register
 Foundation

LON654-0041