

ANNUAL SURVEYS.

29917

1869

No. 28 Survey held at London Date 14 February 1869
 on the bark 'Calcutta' Master Brodie
 Tonnage 324 Built at Rangoon When built 1840
 By whom built Owners Brodie & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Bridge Gays and Afloat

Last Survey, No. 28613 Port of London.

Classed B.A.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper At the When put on 1867

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Yellow Metal Sheathing

Is now in good and efficient condition and
 in my opinion eligible to remain as classed.

Committee's Minute 23 February 1869

Character assigned Cont^d 37 1 V.M.S.

Certificate (if required).

No. 368 Survey held at London Date 15 February 1869
 on the bark 'Mary Evans' Master Thos. G. Gilley
 Tonnage 306 Built at Newcastle When built 1861-4th
 By whom built Hutchins Owners Hutchins & Co
 Port belonging to London Destined Voyage West Indies via Cardiff
 If Surveyed Afloat or in Dry Dock Patched Dry Dock

Last Survey, No. 29342 Port of London.

Classed 7.A.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper At the When put on 1868

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

The two courses of Union Metal that were put on when last surveyed
 now stripped, and repaired on felt, patched Yellow Metal Sheathing.

Is now in good and efficient condition and in my opinion
 eligible to remain as classed.

Committee's Minute 23 February 1869

Character assigned Cont^d 57 1 V.M.S.

Certificate (if required).

LON654-0111