

REPORT of SURVEY for REPAIRS.

29920

No. in Reg. Book. **No.** 123 Survey held at London Date 11th February 1869
 on the bark 'Capitani' Master M. Upton
 Tonnage 533 built at Sunderland When built 1859-9 mo
 By whom built Josh Owners S. Patton
 Port belonging to Shields Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock in Dry Dock

Last Survey, No. 27607 Port London. Classed 10 A 1
cf. 66

REPAIRS

Stripped Yellow Metal sheathing caulked from keel to gunwale and resheathed bottom with Yellow Metal on felt.

Fore topmast and the fore and Main Yards new of Pitch Pine.

Light Metal has been put on just for the voyage, it being the owner's intention to have this ship declared on her return.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained Examined Aloft

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Is now in good and efficient condition, and in my opinion eligible to remain as classed 10 A 1.

The Amount of Fee.....£ : : is received by me,

Special..... / : / : } G.P.

Certificate (if required) : 5 : }

Committee's Minute 26th February 1869

Character assigned 10 A 1

record M.P.



© 2019

Lloyd's Register Foundation

LON654-0114