

29926

Nov 20/69

REPAIRS

Present Condition of the

Decks

Waterways

Coming

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

<i>Anchors</i>	<i>No. of</i>
----------------	---------------

Cables

Hawsers and Warps

Standing & Running Rigging

Where tested

Is now in good and efficient condition and in my opinion eligible to remain as Classed 10 A1.

The Amount of Fee.....£ — : — : is received by me,

Special..... / : / : — *BB*

Certificate (if required) _____

Committee's Minute 26th February 1869

Character assigned

record ~~11/11~~ 9/22

© 2019

Lloyd's Register
Foundation

LON 654-0120