

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 143 Survey held at London Date March 19 ^{4th April} 1869
 on the 43rd West Master W Rossiter
 Tonnage 366 409 built at Sunderland When built 1848
 By whom built _____ Owners Wright & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Globe & W I Dock

Last Survey, No. 30010 Port London Classed 13 A 1

REPAIRS

Cost 61 — 9 ^{3.69}
10.69

Yellow metal repaired.

Windlass slipped see former survey

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>sufficient</u>
Planksheers <u>where seen</u>	Keelsons <u>where seen</u>	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>T & M</u> When put on <u>1866</u>	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel appears eligible in my opinion to remain as classed A 1

Thos. W. Wain

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 23rd April 1869

Character assigned Cont 9 A 1 MAI



© 2019

Lloyd's Register Foundation

LON654-0230