

ANNUAL SURVEYS.

30102

No. 156 Survey held at London Date 26th April 1869
 on the bark "Westbury" Master W. Cook
 Tonnage 329 Built at Sunderland When built 1859 - 7 mo
 By whom built Pile Owners J. Cruickshank
 Port belonging to London Destined Voyage Japan
 If Surveyed Afloat or in Dry Dock Bull Head Dry Dock and Afloat

Last Survey, No. 29634 Port of London Classed 10 A1

The present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper Atm When put on 1868

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Sails
 Anchors No. of
 Cables
 Hawser and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Look where examined

Fore Mast new of Pine. Yellow Metal Sheathing patched.
Is now in good and efficient condition
and in my opinion eligible to remain as classed.

Committee's Minute 11th May 1869

Character assigned 10 A1 WAS

W. H. Warner

Certificate (if required).

No. 183 Survey held at London Date 5th May 1869
 on the Ship "Percy Douglas" Master J. Ramon
 Tonnage 781 Built at Serresy When built 1861 - 8 mo
 By whom built Hayley Owners J. Hayley
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock and Afloat

Last Survey, No. 28318 Port of London Classed 10 A1

The present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper Atm When put on 1867

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Sails
 Anchors No. of
 Cables
 Hawser and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Look where examined

Patched Yellow Metal Sheathing
Is now in good and efficient condition
and in my opinion eligible to remain
as classed.

Committee's Minute 11th May 1869

Character assigned 10 A1 WAS

W. H. Warner

Certificate (if required).

LON654-0271