

# ANNUAL SURVEYS.

30121

No. 1082 Survey held at London Date 19<sup>th</sup> May 1869  
 on the Ship "Mullak" Master P. B. Stephens  
 Tonnage 713 Built at Sunderland When built 1856  
 By whom built Byth & Greene Owners Byth & Greene  
 Port belonging to London Destined Voyage Mauritius  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 20625 Port of London Classed 13A1  
 cf. 9.67

The present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Comings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Upper Deck Beams & Fastenings	Ditto ditto at other places	Sails
Lower Deck Beams & Fastenings	Keelsons	Anchors No. of
Planksheers	Clamps and Shelves	Cables
Sheerstrakes	Ceiling	Hawsers and Warps
Topsides	Rudder	Standing & Running Rigging
Wales	Copper <u>As in</u> When put on <u>1867</u>	
Plank (Bottom) and Counter	Caulking of Bottom, Deck, and Waterways <u>Look where Examined</u>	

General Observations and Opinion,  
Patched Yellow Metal Sheathing  
is now in good and efficient condition  
and in my opinion eligible to remain as classed.  
 Committee's Minute 21<sup>st</sup> May 1869  
 Character assigned 13A1 WAS  
H. H. Turner  
 Certificate (if required).

No. 366 Survey held at London Date 19<sup>th</sup> May 1869  
 on the Ship "Durham" Master J. C. Kerr  
 Tonnage 1286 Built at Palton When built 1864 - 8 mo  
 By whom built Marshall Owners G. Marshall  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Union Dry Dock and Afloat

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed 13A1  
 cf. 5.67

The present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Comings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Upper Deck Beams & Fastenings	Ditto ditto at other places	Sails
Lower Deck Beams & Fastenings	Keelsons	Anchors No. of
Planksheers	Clamps and Shelves	Cables
Sheerstrakes	Ceiling	Hawsers and Warps
Topsides	Rudder	Standing & Running Rigging
Wales	Copper <u>As in</u> When put on <u>1867</u>	
Plank (Bottom) and Counter	Caulking of Bottom, Deck, and Waterways <u>Look where Examined</u>	

General Observations and Opinion,  
Fore yard renewed of Oregon Pine. patched Yellow Metal Sheathing  
is now in good and efficient condition and in my  
opinion eligible to remain as Classed. 13A1.  
 Committee's Minute 21<sup>st</sup> May 1869  
 Character assigned 13A1 WAS  
H. H. Turner  
 Certificate (if required).