

30126

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 148 Survey held at London Date May 7<sup>th</sup> 11<sup>th</sup> 1869  
on the Barque Falcon Master J. Evans  
Tonnage 395 Built at Plymouth When built 1865  
By whom built Moore Owners P. Patmore 2<sup>d</sup> Patmore  
Port belonging to London Destined Voyage   
If Surveyed Afloat or in Dry Dock Bridge dry dock

Last Survey, No. 29381 Port Liverpool Classed 13. A. 1.  
REPAIRS 7.68

Stripped off the whole of the yellow metal sheathing  
Overhauled the caulking up to metal line, took out the broken  
hawsepole from the Port side, fitted a new one  
Resheathed with yellow metal on felts up to 18 ft

## Present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	<u>1/</u>	Breasthooks and Stenson	<u>1/</u>	<u>1/</u>	Pumps	<u>1/</u>
Comings	<u>1/</u>	Transoms, Pointers, and Crutches	<u>1/</u>	<u>1/</u>	Boats	<u>1/</u>
Upper Deck Beams & Fastenings	<u>1/</u>	Timbers of the Frame at the openings	<u>1/</u>	<u>1/</u>	Masts, Yards, &c.	<u>1/</u>
Lower Deck Beams & Fastenings	<u>1/</u>	Ditto Ditto at other places	<u>1/</u>	<u>1/</u>	Condition, how ascertained	<u>1/</u>
Planksheers	<u>1/</u>	Keelsons	<u>1/</u>	<u>1/</u>	Sails	<u>1/</u>
Sheerstrakes	<u>1/</u>	Clamps and Shelves	<u>1/</u>	<u>1/</u>	Anchors No. of <u>3</u>	<u>1/</u>
Topsides	<u>1/</u>	Ceiling	<u>1/</u>	<u>1/</u>	Cables	<u>1/</u>
Wales	<u>1/</u>	Rudder	<u>1/</u>	<u>1/</u>	Hawsers and Warps	<u>1/</u>
Plank (Bottom) and Counter	<u>1/</u>	Copper <u>Set 7<sup>th</sup> 11<sup>th</sup> 1869</u> When put on <u>Now</u>	<u>1/</u>	<u>1/</u>	Standing & Running Rigging	<u>1/</u>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>good where tested.</u>				

She appears to be in good condition, and is in my opinion entitled to  
remain as class'd 13. A. 1.  
Samuel Resnais


The Amount of Fee.....£ — : — : is received by me,

Special..... 1 : 1 : 30<sup>th</sup> 5.69

Certificate (if required) : :

Committee's Minute 25<sup>th</sup> May 18 69

Character assigned 13 A. 1.



© 2019

Lloyd's Register  
Foundation

LONG54-0291



Below

# REPORT OF SURVIVAL FOR REPAIRS



© 2019  
Lloyd's Register  
Foundation