

30221

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 75 Survey held at London Date 2nd July 18 69
 on the Ship "Saint Vincent" Master Wm. A. Duff
 Tonnage 892 built at Sunderland When built 1865 - 7 mo
 By whom built Pile Owners Peritt & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Union dry dock and afloat

Last Survey, No. 29257 Port Low Classified 12 A1
 REPAIRS Iron Frame Plank Expt 138 6.68.
A.I.B.

Shipped Yellow Metal Sheathing, caulked butts of bottom, garboard seams and hooding ends and re-sheathed bottom with Yellow Metal on paper.

Not any iron bolts under Metal

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>—</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>—</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>—</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>Seen from the deck</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>Yellow Metal</u> When put on <u>now</u>	Standing & Running Rigging	<u>Good</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.		<u>Good where tested</u>

Is now in good and efficient condition and in my opinion eligible to remain as Classed 12 A1.

The Amount of Fee.....£ : : is received by me,

Special..... / : /

Certificate (if required) : 5 :

Committee's Minute 9th July 18 69

Character assigned 12 A1

record G.M. W.S.

