

REPORT of SURVEY for REPAIRS.

30288

No. in Reg. Book. **No.** 539 Survey held at London Date 26th July & 4th Aug^r 1869
 on the Ship Singala Master C. Neilson
 Tonnage 799 Built at Workington When built 1865
 By whom built Lampart Owners W. Nicol
 Port belonging to Liverpool Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Fletcher's dry dock

Last Survey, No. 28189 Port Liverp. Classed 14. A. 1.

REPAIRS

Stripped off the whole of the Yellow Metal
 baulked from keel to Metal line, and resheathed
 with Yellow Metal on Felt. Lifted Rudder to
 repair deck pintle.

Survey'd her with part Cargo on board.

Present Condition of the

Decks <u>good</u>	Treenails <u>where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>3</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>7 1/2 lbs</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. where tested good

As far as seen she appears to be in good condition. and is
 in our opinion entitled to remain as classed. 14 A. 1.

The Amount of Fee.....£ - : - is received by me,

Special..... 1 : 1 : } Asd

Certificate (if required) : 5 : }

Committee's Minute 13th August 18 69

Character assigned 14th Aug
revised G.M. W.A.

J. Lawrence
James Presnall



© 2019

Lloyd's Register
 Foundation

LN654-0421

Angala



© 2019

Lloyd's Register
Foundation