

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 358 Survey held at London Date Aug^r 31st Sep^r 29th 1869
 on the Ship Sea Star Master J. A. Varcy,
 Tonnage 654 built at Aberdeen When built 1855
 By whom built _____ Owners Hutchinson
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock "Horse Ferry" dry dock

Last Survey, No. 30332 Port Lon. Classed Cont^d/64 C.A. 1.

REPAIRS

Visited and surveyed this vessel on account of leakage proved to have arisen from some hole having been left wilfully open, or otherwise. or partly from the caulking.

The whole of the Yellow Metal Sheathing has now been stripped off, the caulking tested, and found unsatisfactory. She has been recaulked, and the caulking retasted, and carefully overhauled throughout, and all made good and efficient, and resheathed with Yellow Metal on felt. — She is reported to have been last sheathed &c at the Mauritius. —

Present Condition of the

Parts	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stenson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	firm	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from the Deck
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of 3 &	"
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	efficient	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	Fe ^l & Y ^m When put on	now	Standing & Running Rigging	"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested.

As far as seen She is now in good condition and is in my opinion entitled to remain as classed Cont^d/64, C.A. 1.

The Amount of Fee.....£ — : — : is received by me,

Special..... 1 : 1 :

Certificate (if required) : 5 :

Committee's Minute 5th October 1869

Character assigned Cont^d 4 1

Samuel Persons

© 2021

Lloyd's Register Foundation

LON 655-0016

Sea Star

REPORT OF STEWARD

No. 1000
on the
Tonnage
By whom built
First delivery to
The shipping agent

Last entry to
REPAIRS

Present condition of the
Hull
Machinery
Electrical
Engine
Boiler
Superstructure
Deck
Cargo
Stores
Fuel
Water
Provisions
Medical
Tools
Other
Remarks

The statement of the
Special
Certificate if required
Signature of Steward