

30405

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 1st Sept Last Survey 4 October 1869
on the Ship "Willloomooloo" Master Anderson
Tonnage 645 built at Aberdeen When built 1852
By whom built N. Wood Owners Thompson & Norman Ganson
Port belonging to Aberdeen Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Wigram's Dry Dock and Afloat.
Last Survey, No. 28829 Port Lon. Classed 10 A1.
REPAIRS, &c. Cont^d 52-7 yrs.
"H.T. 67" 12.57.

Windlass unhand, wood linings stripped. One upper deck beam renewed, and two ditto scarphed, of Pitch Pine. Main-waterway renewed, on each side, from fore mast. Obseak of deck of Pitch Pine, and flat of upper deck of 4th Yellow Pine, the strake next waterway being of Baltic Fir 5th thick. caulked from metal line over all, and patched Yellow Metal sheathing.

Mizen Mast taken out and a new one supplied of Pitch Pine.

Present Condition of the

Deck <u>new</u>	Treenails	Windlass and Capstan <u>Good</u>
Waterways <u>as fast</u>	Breasthooks and Stenson	Pumps <u>—</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>—</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>—</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>Examined Afloat</u>
Planksheers	Keelsons	Sails <u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>Good</u>
Topsides	Ceiling	Cables <u>and</u>
Wales	Rudder	Hawsers and Warps <u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>4 1/2 in</u> When put on <u>1867</u>	Standing & Running Rigging <u>Good</u>
Engine Room Skylights	Caulking of <u>Good where</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Good</u>	Hatches <u>Good</u>
General Observations and Opinion,	Scuppers <u>Good</u>	

Is now in good and efficient condition and in our opinion eligible to remain as Classed.

The Amount of Entry Fee.....£ 2 : — : — is received by me.
Special.....£ 2 : 2 : 2
Certificate (if required) : 5
Committee's Minute 5th October 1869
Character assigned Cont^d 7 1/2
record repair

J. H. Eastlake.

LOA 655-0022