

# ANNUAL SURVEYS.

30400

*Rev. J. J. Done*

No. 473 Survey held at London Date 7<sup>th</sup> to 16<sup>th</sup> October 1869  
 on the Barque "Brinkburn" Master W. Kunciman  
 Tonnage 540 Built at Sunderland When built 1866. 3 mo.  
 By whom built Davis' n Owners Loram & Co  
 Port belonging to Sunderland Destined Voyage Alexandria  
 If Surveyed Afloat or in Dry Dock New Crane Dry Dock and Chadwell Basin

Last Survey, No. 28616 Port of Lor. Classed 10.A.1.  
(7-67)

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good when seen</u>	Windlass and Capstan <u>Good and sufficient</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>Good when seen</u>	Keelsons <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>Good, New Tiller and 3 clasp hoops fitted</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Yellow Metal</u> When put on <u>1867</u>	

General Observations and Opinion,

The Yellow Metal sheathing, in many places, was much worn; about 400 sheets were used in patching it.  
 Is in good condition, and in my opinion eligible to remain as classed (viz) 10.A.1

Committee's Minute 26<sup>th</sup> October 1869.

*J. J. Done*

Character assigned 10.A.1 MMS

Certificate (if required).

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18 \_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_

Character assigned \_\_\_\_\_

Certificate (if required).