

# ANNUAL SURVEYS.

30649

No. 176 Survey held at London Date 21<sup>st</sup> January 1870  
 on the Ship "Devana" Master J. Thomson  
 Tonnage 795 Built at Aberdeen When built 1864, 11 mo.  
 By whom built Hall Owners J. Jamieson  
 Port belonging to Aberdeen Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Linehouse, Dry Dock

No. 26. 1. 70

Last Survey, No. 29690 Port of London Classed 13.A.1  
 (12-68)

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	<del>Copper</del> <u>Z. Mc</u> When put on <u>1868</u>	

Good where seen

Good where seen

Good and sufficient

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Bottom now sighted and yellow metal patched.

She is in good and efficient condition and in my opinion fit to remain as classed  
 (viz) 13.A.1

Committee's Minute 28<sup>th</sup> January 1870  
 Character assigned 13A.1

*J. M. J. Bone*

*J. M. J. Bone*

Certificate (if required)

No. 160 Survey held at London Date 13<sup>th</sup> to 24<sup>th</sup> January 1870  
 on the Ship "Timroud" Master J. Lowther  
 Tonnage 760 Built at Scarborough When built 1853  
 By whom built Lindalls Owners R. Morris  
 Port belonging to London Destined Voyage Kurrachee  
 If Surveyed Afloat or in Dry Dock Linehouse, Dry Dock and West India Docks

Last Survey, No. 1549 Port of Bideford Classed 13.A.1 Contd 66-9A.1  
 (6-68)

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>New fibboom</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder <u>New main piece</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<del>Copper</del> <u>Z. Y. Mc</u> When put on <u>1868</u>	

Good where seen

Good where seen

Good and sufficient

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Yellow metal patched; the butts of Topsides caulked and a new main piece fitted to the Rudder, of Seal.

She is in good and efficient condition, and in my opinion fit to remain as classed viz: -  
 Contd 66-9A.1

Committee's Minute 28<sup>th</sup> January 1870  
 Character assigned Contd 9A.1

*J. M. J. Bone*

*J. M. J. Bone*

Certificate (if required).

