

30685

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 407 No. 27407 Survey held at London Date, first Survey 13 Dec 1869 Last Survey 5 Feb 70 18 70
on the Ship Seringapatam Master H. Wyeth
Tonnage 587 built at Greenock When built 1849
By whom built A Owners Soley etc
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Princes Bay Dock and afloat.

Recd 1870

Last Survey, No. 27407 Port Lon. Classed 13 - A \ exposed
REPAIRS, &c. of Boat 4 yrs 5.66

Keels partially cleaned, the timbers in way of same lifted. One plank of Sipside split out all fore and aft on each side, as also a short plank in each buttock.

The following defects were found viz:-

Quarter Timber, one fore hood and one after hood of Sipside together with a portion of the Mahogany planking, portside, in Starb. Buttock. Stern Frame, Port

The Owners attention having been drawn to the above he gave directions not to proceed any further with the Survey and she has since been removed to the West India Dock
J. A. Turner.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations and Opinion,	Scuppers	Cargo and Main Hatchways
		Hatches

The Amount of Entry Fee.....£ : : is received by me,
Special..... : :
Certificate (if required) : :

Committee's Minute 15th February 1870
Character assigned Discharged

LONGSS-0224