

# ANNUAL SURVEYS.

30/25

No. 130 Survey held at London Date 2<sup>nd</sup> March 1870  
 on the Barque "Wellington" Master P. In Rster.  
 Tonnage 533 Built at Lunderland When built 1847  
 By whom built                      Owners Limpson  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock Line Rln Dry Dock.

Last Survey, No. 29933 Port of Lon.

Classed Rest 61-74 A.1  
Cont. 68-24 A.1  
(2-69)

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> <u>Felt &amp; Y. M.</u> When put on <u>1868</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good

Yellow metal patched.

She is in good and efficient condition and in my opinion fit to remain as classed viz:- Contd 68-24 A.1

Committee's Minute 8<sup>th</sup> March 1870

J. F. Bone

Character assigned Contd 2 A.1

Certificate (if required)

No. 500 Survey held at London Date 3<sup>rd</sup> March 1870  
 on the Brig "Melba" Master Hamlyn  
 Tonnage 257 Built at London When built 1838  
 By whom built Wigram Owners Scrutton Sons &  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 30341 Port of Lon.

Classed Contd 68-74 A.1  
(18-69)

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> When put on <u>                    </u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good

Bottom sighted, and yellow metal patched.

She is in good and efficient condition, and in my opinion, fit to remain as classed viz:- Contd. 68. 74 A.1.

Committee's Minute 8<sup>th</sup> March 1870

J. F. Bone

Character assigned Contd 7 A.1

Certificate (if required).