

REPORT of SURVEY for REPAIRS.

30767
Recd. 7. 4. 80

No. in Reg. Book. **No.** Survey held at London Date, first Survey 1 Last Survey March 28 1870
on the 13th Weymouth Master C. P. Jones
Tonnage 521 built at London When built 1854
By whom built _____ Owners W H Sindall
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 28959 Port Lon. Classed 13A1
REPAIRS, &c. Rest by 13 2-68

In West's dry dock, the yellow metal sheathing stripped off, recaulked from keel to upper part of doublers, also three seams of topsides and the waterway seam and the yellow metal renewed on the floor'd bottom —

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>SM</u> When put on <u>now</u>	Standing & Running Riggings
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>good when sea</u>	
General Observations and Opinion,	Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>	

This vessel is eligible in my opinion to remain as classed 13A1

Mos. W. Wain

The Amount of Entry Fee.....£ — is received by me,

Special.....

Certificate (if required)

Committee's Minute 8th April 18 70

Character assigned Rest 13
Cont recd. S.M.



© 2021

Lloyd's Register
Foundation

LON 655-0277