

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 33 Survey held at London Date 25th 27th March 18⁶⁸
on the Ship Rajah of Sarawak Master S. J. R. Norton
Tonnage 484 built at Bideford When built 1850
By whom built — Owners Widdicombe & —
Port belonging to Liverpool Destined Voyage Brisbane
If Surveyed Afloat or in Dry Dock Fountain dry dock & London docks.

Last Survey, No. 18828 Port Liv. Classed Con^{1st}/63. G.A.I.

REPAIRS

Surveyd her in ballast.

Stripped off the whole of the Yellow Metal Sheathing
Cleared the middle line as far as practicable, lifted the
limbers, examined floors and keelson, and a good portion of
the lower hold ceiling planks. Caulked the outside up
to Copper line. Resheathed with yellow metal on felt.
Owners declined for the present, 'or until she returns,' going
in for the half time Survey Rule. —

Condemned the main mast, introduced a new
one of Yellowpine and refitted the rigging.

Present Condition of the

Decks <u>good</u>	Treenails <u>where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>new main</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>on enquiry and as from the deck</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>resheathed</u> When put on <u>now</u>	Standing & Running Rigging <u>refitted.</u>
General Observations and Opinion, <u>—</u>	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>	

I am of opinion this Vessel is entitled to remain as
Class'd Con^{1st}/63, G.A.I.

Samuel Nelson

The Amount of Fee.....£ — : — : is received by me,

Special..... 2 : 2 : —

Certificate (if required) : 5 : —

Committee's Minute 14 April 18 70

Character assigned Port 9



© 2021

Lloyd's Register
Foundation

LON 655 0290

Regist. of Sarawak



© 2021

Lloyd's Register
Foundation