

# ANNUAL SURVEYS.

30949  
Rev 2/1/70

No. 352 Survey held at London Date 30<sup>th</sup> May - 29<sup>th</sup> June 1870  
on the Ship "Alnwick Castle" Master De Carteret  
Tonnage 1087 Built at Sunderland When built 1856  
By whom built — Owners H. Green  
Port belonging to London Destined Voyage Melbourne  
If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock

Last Survey, No. 30098 Port of Lon. Classed 13 A 1.  
Cont. 69-9.  
4, 69.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>2 1/2</u> M. When put on <u>189.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Yellow metal patched, and coated with Peacock's Composition. Recaulked  
butts of topsides. New fore-castle deck of 3" Dantie Fir.  
Is now in good and efficient condition, and fit in my opinion to  
remain as classed - Continued 189-9 yrs.

J. H. Eastlake;

Committee's Minute 5<sup>th</sup> July 1870

Character assigned Cont 9 A 1

Certificate (if required).

No. 126 Survey held at London Date 29<sup>th</sup> June - 1<sup>st</sup> July 1870  
on the Ship "The Lord Warden" Master J. Smith  
Tonnage 1237 Built at Sunderland When built 1862  
By whom built Pile Owners R. Green  
Port belonging to London Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock

Last Survey, No. 29465 Port of Lon. Classed 13 A 1.  
H.T. 68.  
9, 68.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>2 1/2</u> M. When put on <u>188.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Yellow metal patched, and coated with Peacock's Composition.  
Recaulked butts in topsides and deck, also the waterway beams.  
Is now in good and efficient condition, and fit in my opinion  
to remain as classed - 13 A 1.

J. H. Eastlake.

Committee's Minute 5<sup>th</sup> July 1870

Character assigned 13 A 1

Certificate (if required).



Lloyd's Register  
Foundation

30949-0403