

# REPORT of SURVEY for REPAIRS.

30970

No. in  
Reg. Book.

No.

Survey held at

London

Date, first Survey

May 6<sup>th</sup>

Last Survey

June 17<sup>th</sup> 1870

on the

Ship Lincelles

Master

Neghtholm

Tonnage

904

built at

Moulmein

When built

1838

By whom built

Owners

J. Allan

Port belonging to

London

Destined Voyage

Colombo

If Surveyed Afloat or in Dry Dock

Limekiln Dry Dock & West India Dock

Last Survey, No.

20570

Port

Lon.

Classed

15A.1.

REPAIRS, &c.

Now done, the yellow metal sheathing renewed upon  
Selt. the keel caulked from keel to gunwale, the  
buttresses extra bolted, and the Hawse Pipes renewed.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations and Opinion,

Treenails

Breasthooks and Stems

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Budder

Copper

Bottom, Deck, & Waterways

Scuppers

Cargo and Main Hatchways

Hatches

Standing & Running Rigging

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

x Shipped 1866

x Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained by examination  
from deck & enquiry -

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

Good and

sufficient

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

Good where

seen

The Amount of Entry Fee.....£ - : - : is received by me.

Special..... / : / : }

Certificate (if required) : 5 : }

Committee's Minute

15<sup>th</sup> July

18

Character assigned

15<sup>th</sup> /

received  
WMA



© 2021

Lloyd's Register  
Foundation

LON 655-0412