

31014

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 819 Survey held at London Date July 28th 18 70
on the S. Costa Rica Packet Master R. Pope
Tonnage 531 built at Guernsey When built 1861
By whom built _____ Owners Le Sackeur
Port belonging to Guernsey Destined Voyage Armas
If Surveyed Afloat or in Dry Dock Globe dry dock & St Katharine's Dock

Last Survey, No. 29520 Port London Classed 15 A 1
H.T.B.P. 8.68

REPAIRS

The yellow metal sheathing stripped off, resaulted from keel to metal line and the yellow metal renewed on paper on the upper courses and on felt below—

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Good	Ditto Ditto at other places		Condition, how ascertained	Good & sufficient
Planksheers		Keelsons	Good	Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		When put on <u>now</u>		Standing & Running Riggings	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	good where tested		

This vessel is now in a good and efficient state and eligible in my opinion to remain classed 15 A 1

The Amount of Fee.....£ — : — : is received by me,
Special..... 1 : 1 :
Certificate (if required) — : — :
Thos. W. Nawn

Committee's Minute 5th August 18 70
Character assigned 15 A 1