

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 211 Survey held at London Date July 29<sup>th</sup> 1870  
 on the S<sup>r</sup> "Houmahal" Master J. Fowler  
 Tonnage 841 built at Bridport When built 1856  
 By whom built \_\_\_\_\_ Owners Peruse  
 Port belonging to Liverpool Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock London & East India Docks

Last Survey, No. 30270 Port Liver. Classed 13A1  
 Cont 69 — 9 7.69

## REPAIRS

In consequence of damage, see Special report;  
 the whole of the main Rails, bulwarks and  
 poop fittings renewed, and the ship recaulked  
 from metal line overall —

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Good and</u>
Planksheers <u>where seen</u>	Keelsons <u>where seen</u>	Sails <u>sufficient</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of _____
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>T.S.M.</u> When put on <u>1869</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>	

This vessel is eligible, in my opinion, to  
 remain as classed A 1

The Amount of Fee.....£ — : — is received by me,

Special..... — : —

Certificate (if required) : :

Committee's Minute 5<sup>th</sup> August 1870

Character assigned Cont<sup>d</sup> 9 A 1

Damage Special paid  
£5.5.0



© 2021

Lloyd's Register  
 Foundation

NON 655-0445