

ANNUAL SURVEYS.

31/39

No. 253 Survey held at London Date Sept 14th 22nd 1870
 on the Ship Dover Castle Master W. F. Owen
 Tonnage 1002 Built at Sunderland When built 1858
 By whom built _____ Owners R. Green
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greens upr Dock

Recd 27.9.70

Last Survey, No. 20695 Port of London Classed 13. A. 1. 5.69

The present Condition of the

Decks <u>good</u>	Treenails <u>where seen</u>	<u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>11</u>	Breasthooks and Stemson <u>11</u>	<u>11</u>	Pumps <u>11</u>
Comings <u>11</u>	Transoms, Pointers, and Crutches <u>11</u>	<u>11</u>	Boats <u>11</u>
Upper Deck Beams & Fastenings <u>11</u>	Timbers of the Frame at the Openings <u>11</u>	<u>11</u>	Masts, Yards, &c. <u>11</u>
Lower Deck Beams & Fastenings <u>11</u>	Ditto ditto at other places <u>11</u>	<u>11</u>	Sails <u>11</u>
Planksheers <u>11</u>	Keelsons <u>11</u>	<u>11</u>	Anchors No. of <u>3 & 1 S. 2 K</u> <u>11</u>
Sheerstrakes <u>11</u>	Clamps and Shelves <u>11</u>	<u>11</u>	Cables <u>11</u>
Topsides <u>11</u>	Ceiling <u>11</u>	<u>11</u>	Hawsers and Warps <u>11</u>
Wales <u>11</u>	Rudder <u>efficient</u>	<u>11</u>	Standing & Running Rigging <u>11</u>
Plank (Bottom) and Counter <u>11</u>	Copper <u>11</u>	When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Sighted the Bottom patched the yellow metal sheathing.
Caulked the topsides, and waterway, - repaired the main hatchway Comings
also the after hatchway. - As far as seen she appears to be in good
condition, and I am of opinion she is entitled to remain as classed
 Committee's Minute 30th September 1870 13. A. 1. 5.69

Character assigned

13 A 1 M

Samuel Parsons

Certificate (if required).

No. 369 Survey held at London Date Sept 15th 22nd 1870
 on the Ship Hotspur Master J. Porteous
 Tonnage 1142 Built at Newcastle When built 1851
 By whom built J. Smith Owners Southern & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Greens upper dock.

Last Survey, No. 24235 Port of _____ Classed 13. A. 1.

Cont 64: 9 5.68

The present Condition of the

Decks <u>good</u>	Treenails <u>where seen</u>	<u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>11</u>	Breasthooks and Stemson <u>11</u>	<u>11</u>	Pumps <u>new in 1867</u> <u>11</u>
Comings <u>11</u>	Transoms, Pointers, and Crutches <u>11</u>	<u>11</u>	Boats <u>11</u>
Upper Deck Beams & Fastenings <u>11</u>	Timbers of the Frame at the Openings <u>11</u>	<u>11</u>	Masts, Yards, &c. <u>new mizen mast</u> <u>11</u>
Lower Deck Beams & Fastenings <u>11</u>	Ditto ditto at other places <u>11</u>	<u>11</u>	Sails <u>11</u>
Planksheers <u>11</u>	Keelsons <u>11</u>	<u>11</u>	Anchors No. of <u>3 & 1 S. 2 K</u> <u>11</u>
Sheerstrakes <u>11</u>	Clamps and Shelves <u>11</u>	<u>11</u>	Cables <u>11</u>
Topsides <u>11</u>	Ceiling <u>11</u>	<u>11</u>	Hawsers and Warps <u>11</u>
Wales <u>11</u>	Rudder <u>efficient</u>	<u>11</u>	Standing & Running Rigging <u>11</u>
Plank (Bottom) and Counter <u>11</u>	Copper <u>11</u>	When put on <u>1868</u>	

General Observations and Opinion, Y. P.

Caulking of Bottom, Deck, and Waterways good

Introduced a new 1 1/2 inch masts
Overhauled the Pumps.
paid the 4 masts with Brasco's
Anti Corrosive.
patched yellow metal.
 Committee's Minute 30th September 1870
 Character assigned Cont. 9 A 1

Samuel Parsons

Certificate (if required).

Lloyd's Register Foundation

Wolsper
James Caille



© 2021

Lloyd's Register
Foundation