

# Continuation 1st Rule

## REPORT of SURVEY for REPAIRS.

31151

in Book. No. 50 Survey held at London Date September 24<sup>th</sup> 1870  
 on the "Surrey" Master \_\_\_\_\_  
 Tonnage 1089 built at Shields When built 1857  
 By whom built \_\_\_\_\_ Owners Marshall & Co  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock London Dock & Millwall Dry Dock.

Survey, No. 30174 Port London Classed 13 A 1  
 (H.T. 69.) 6.69

Outside planking from Light water mark to the waterway  
 seams scraped or dished bright, a listing four inches wide  
 opened at each end of the hold on both sides, one fifth the  
 entire length of the ship; timbers lifted, air courses opened  
 and the frame found all good, treenails driven out and  
 found good, the windlass stripped and chains cauged  
 last survey in 1869.

In consequence of Damage, the yellow metal sheathing  
 stripped off, and the vessel recaulked from keel to metal  
 line and resheathed with yellow metal on felt.

Condition of the

ways		Treenails		Windlass and Capstan	
gs		Breasthooks and Stemson		Pumps	
Deck Beams & Fastenings		Transoms, Pointers, and Crutches		Boats	
Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
sheers	Good	Ditto Ditto at other places	Good	Condition, how ascertained	Good &
okes		Keelsons		Sails	Sufficient
		Clamps and Shelves		Anchors No. of <u>3x1x2</u>	
		Ceiling		Cables <u>300 Fathoms</u>	
		Rudder		Hawsers and Warps	
(Bottom) and Counter		Copper <u>Put on when put on 70</u>		Standing & Running Rigging	

Observations and Opinion,

This vessel being now in a good and efficient state of repair, and  
 having complied with the rule for continuation, Section 54 No 1,  
 except as regards the windlass and chains which was complied  
 with in 1869, we beg respectfully to recommend that she be

Amount of Fee.....£ 5 : : is received by me,

Special..... 4 : 4 : 4/10/70

Certificate (if required) : 5 :

Committee's Minute 7<sup>th</sup> October 1870

Factor assigned Cont. for 4 years  
second year

Continued 4 A 1

Jos. W. Wain

W. Wain



© 2021

Lloyd's Register  
Foundation

LONG56 - 0081