

# ANNUAL SURVEYS.

31/80

No. 323 Survey held at London Date 12<sup>th</sup> 24<sup>th</sup> Feb. 1870  
 on the Ship "Mars" Master G. Holman  
 Tonnage 721 Built at Sunderland When built 1856  
 By whom built Owners J. Allan  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Amelita Dry Dock

Last Survey, No. 30330 Port of Lon.

Classed 13A1

The present Condition of the

Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter

Treenails  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper 4<sup>th</sup> When put on 1869

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails  
 Anchors No. of  
 Cables  
 Hawsers and Warps  
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Llor Metal sheathing caulked batts of Lopsides  
 Is now in good and efficient condition and in my  
 opinion eligible to remain as classed.

Committee's Minute 25<sup>th</sup> October 1870

Character assigned Cont 9 1<sup>st</sup> M

Certificate (if required)

No. 150 Survey held at London Date 14<sup>th</sup> Dec. 1870  
 on the Ship "Ben Buck Green" Master J. Penwell  
 Tonnage 544 Built at Corros When built 1846  
 By whom built Owners Rhyth's & Co  
 Port belonging to London Destined Voyage Mauritius  
 If Surveyed Afloat or in Dry Dock Amelita Dry Dock

Last Survey, No. 30603 Port of Lon.

Classed 12

The present Condition of the

Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter

Treenails  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper 4<sup>th</sup> When put on 1869

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails  
 Anchors No. of  
 Cables  
 Hawsers and Warps  
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Llor Metal sheathing caulked waterway seam  
 Is now in good and efficient condition and in my  
 opinion eligible to remain as classed.

Committee's Minute 25<sup>th</sup> October 1870

Character assigned 1<sup>st</sup> M

Certificate (if required).