

ANNUAL SURVEYS.

31/80

No. 323 Survey held at London Date 12th 24th Feb. 1870
 on the Ship "Mars" Master G. Holman
 Tonnage 721 Built at Sunderland When built 1856
 By whom built Owners J. Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Amelida Dry Dock

Last Survey, No. 30330 Port of Lon.

Classed 13A1

The present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper When put on 1869

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Sails
 Anchors No. of
 Cables
 Hawsers and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Lullor Metal sheathing caulked batts of Lopsides
 Is now in good and efficient condition and in my
 opinion eligible to remain as classed.

Committee's Minute 25th October 1870

Character assigned Cont 9 1/2

Certificate (if required)

No. 150 Survey held at London Date 14th Dec. 1870
 on the Ship "Ben Buck Green" Master J. Penwell
 Tonnage 544 Built at Corros When built 1846
 By whom built Owners Rhyth's & Co
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Amelida Dry Dock

Last Survey, No. 30603 Port of Lon.

Classed 12

The present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper When put on 1869

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Sails
 Anchors No. of
 Cables
 Hawsers and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Lullor Metal sheathing caulked waterway seam
 Is now in good and efficient condition and in my
 opinion eligible to remain as classed.

Committee's Minute 25th October 1870

Character assigned 1 1/2

Certificate (if required).