

REPORT of SURVEY for REPAIRS.

31258

No. in Reg. Book. 148 No. Survey held at London Date, first Survey 9th Feb^r Last Survey Feb^r 22nd 1870
 on the Composite Ship Carnatic Master J & J. Wait Boyd
 Tonnage 871 built at Sunderland When built 1867
 By whom built Pile Owners J. J. Wait
 Port belonging to North Shields Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Canal dry dock
 Last Survey, No. 30500 Port Lon. Classed 16. A. 1.
10. 69

REPAIRS, &c.

*Stripped off the whole of the Yellow metal Sheathing
 Resheathed with Yellow metal on felt.*

Present Condition of the

Decks	<i>good</i>	Treenails	<i>Bolts</i>	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	<i>from the deck</i>
Planksheers	"	Keelsons		"	Sails	"
Sheerstrakes	"	Clamps and Shelves		"	Anchors No. of	<i>3 & 15. 21K</i>
Topsides	"	Ceiling		"	Cables	"
Wales	"	Rudder	<i>efficient</i>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<i>See Hymle</i>	<i>When put on now</i>	Standing & Running Rigging	"
Engine Room Skylights		Caulking of		<i>good</i>		
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways				
General Observations and Opinion,		Scuppers	<i>good</i>		Cargo and Main Hatchways	<i>good</i>
					Hatches	<i>good</i>

*As far as seen she appears to be in good condition
 and is in my opinion entitled to remain as Class'd 16. A. 1.
 Samuel Parsons*

The Amount of Entry Fee.....£ - : - : } is received by me,
 Special..... 2 : 2 : }
 Certificate (if required)..... : : : }

Committee's Minute *6th December 1870*

Character assigned *16 A 1 second M*
Wt



© 2021

Lloyd's Register
 Foundation

LON656-0154

Carnatic



© 2021

Lloyd's Register
Foundation