

ANNUAL SURVEYS.

31440

No. 34 Survey held at London Date 18th Feb^y 1871
 on the "Park Falcon" Master J. Evans
 Tonnage 395 Built at Plymouth When built 1865-4mo
 By whom built Moore Owners P. Patmore
 Port belonging to London Destined Voyage Cape of Good Hope
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 30126 Port of Lon. Classed 13 A1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>14th Mo</u> When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Yellow Metal Sheathing
Is now in good and efficient condition
and in my opinion eligible to remain as flagged.

Committee's Minute 28th February 1871

Character assigned 13 A1

M. A. Burnes

Certificate (if required).

No. 129 Survey held at London Date 21st Feb^y 1871
 on the "Park Flying Fish" Master G. D. Taylor
 Tonnage 393 Built at Swansea When built 1858
 By whom built London Owners Colonial Company Limited
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 30770 Port of Lon. Classed 13 A1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>14th Mo</u> When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Yellow Metal Sheathing
Is now in good and efficient condition
and in my opinion eligible to remain as flagged.

Committee's Minute 28th February 1871

Character assigned 13 A1

M. A. Burnes

Certificate (if required).