

No. 476 Survey held at London Date 15th March 1871
on the ship "Pundalee" Master James Ramsay
Tonnage 921 Built at Aberdeen When built 1869-3mo
By whom built Humphrey Owners Johnson & Co
Port belonging to Aberdeen Destined Voyage Adelaide
If Surveyed Afloat or in Dry Dock Lincolnton dry dock.

31480

Last Survey, No. 30758 Port of Lon.

Classed G.A.1

3.70

present Condition of the

s
erways
ings
er Deck Beams & Fastenings
er Deck Beams & Fastenings
aksheers
erstrakes
sides
les
nk (Bottom) and Counter

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper Asm When put on 1869

Windlass and Capstan

Pumps
Boats
Masts, Yards, &c.
Sails
Anchors No. of
Cables
Hawsers and Warps

Standing & Running Rigging

Caulking of Bottom, Deck, and Waterways

General Observations and Opinion,

Patches Yellow Metal Sheathing
is now in good, and efficient condition.
and in my opinion eligible to remain as classed.

Committee's Minute

21st March 1871

Character assigned

G.A.1
88

W. H. Burnes

Certificate (if required).

LON656-0285