

# REPORT of SURVEY for REPAIRS.

\* 31501

No. in Reg. Book. 177 No. 30053 Survey held at London Date, first Survey March 1871 Last Survey March 1871  
 on the "West" Master Rossiter  
 Tonnage 409 built at Sunderland When built 1848  
 By whom built          Owners C. W. Day & Co.  
 Port belonging to London Destined Voyage South America  
 If Surveyed Afloat or in Dry Dock Globe dry dock & N.E. Dock  
 Last Survey, No. 30053 Port London Classed 13 A B

REPAIRS, &c.

Yellow metal stripped off, recaulked throughout and resheathed with yellow metal or felt — a few trenails driven out of the upper course and found good —

The owner declined at present to reclass but wished the metal to be reported —

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations and Opinion,	Scuppers	Cargo and Main Hatchways
		Hatches

*Thos. W. Wawn*

The Amount of Entry Fee.....£..... is received by me,

Special..... / : / : *[Signature]*  
 Certificate (if required) — : — :

Committee's Minute *[Signature]* 18

Character assigned West India Dock Road



© 2021

Lloyd's Register Foundation

LON656-0303