

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.
583

No.

Survey held at

London

Date, first Survey

Mar: 1st

Last Survey

April 3rd
March 24 1871

on the

4th "Eudora"

Master

W Turnbull

Tonnage

322

built at

Montrose

When built

1864

4 mo.

By whom built

Binnie

Owners

Forthner &

Port belonging to

London

Destined Voyage

Natal

If Surveyed Afloat or in Dry Dock

Fountain dry dock & St Katharines dock

Last Survey, No.

30094

Port

Low.

Classed

10 A 1

(H.T.69.)

5-59

REPAIRS, &c.

The yellow metal stripped off, recaulked from keel to metal line and the yellow metal renewed on felt.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations and Opinion,

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Hatches

This vessel is eligible, in my opinion, to remain as classed A 1

Thos. W. Wain

The Amount of Entry Fee.....£

Special.....

Certificate (if required)

Committee's Minute

12th May

1871

Character assigned

10 A 1

record & M



© 2021

Lloyd's Register

Foundation