

Half Time 31598

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 485 No. 1 Survey held at London Date, first Survey April 24th Last Survey May 9th 1877

on the S. "Burton Stather" Master "Charles Warren"

Tonnage 421 built at "Burton Stather" When built 1866

By whom built _____ Owners Bullard & Co

Port belonging to London Destined Voyage Natal

If Surveyed Afloat or in Dry Dock Horseferry dry dock & St Katharines Dock

Last Survey, No. 30286 Port Lon. Classed 9 A 1 8.69

REPAIRS, &c.

In consequence of grounding in special Report.
yellow metal stripped, hung in shores, recaulked
from keel to metal line and reshathed with yellow
metal on felt - Caulked from plank sheers down to
metal -

Half Time

Scraped bright where required Treenails and bolts*
driven out (good) listings cut out in the hold and
the frame found all good. limbers and air courses opened
(good) Windlass stripped chains ranged and all other
Clauses of the Rules complied with -

* All the bolts were found good except a range close above the
metal which have now been renewed with yellow metal.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Plank sheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of 3x1x2
Spikes	Ceiling	Cables 240 fms
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper 1" x 8" When put on now	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunkers, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations and Opinion,

This vessel is now in a good and efficient state
of repair, and is eligible in my opinion to remain as classed

9 A 1
and be marked (HT. 71)

The Amount of Entry Fee.....£ : : is received by me,

Special..... 2 : 2 :

Certificate (if required) : 5 :

Committee's Minute 16th May 1877

Character assigned 9 A 1 HT 71

Damage 2.2



© 2021

Lloyd's Register
Foundation

LON656-0361