

REPORT of SURVEY for REPAIRS.

31646

No. in Reg. Book. 497 No. 30922 Survey held at London Date, first Survey May 4th Last Survey May 30th 1871
 on the S. Ann Ruthie Master A. Burnie
 Tonnage 993 built at Aberdeen When built 1868
 By whom built _____ Owners Ruthie &
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Since dry dock & London Dock
 Last Survey, No. 30922 Port Low. Classed 14 A 1
 6, 70

REPAIRS, &c.

Yellow metal sheathing stripped off, recaulked from keel to metal line and the yellow metal sheathing renewed on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <i>Good</i>	Ditto Ditto at other places <i>Good</i>	Condition, how ascertained
Planksheers <i>where seen</i>	Keelsons	Sails <i>Sufficient</i>
Sheerstrakes	Clamps and Shelves <i>where seen</i>	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <i>TYNE</i> When put on <i>now</i>	Standing & Running Rigging
	Caulking of	
	Bottom, Deck, & Waterways <i>good</i>	
Engine Room Skylights	Coat Bunker, Openings, Lids, &c.	Scuppers
		Cargo and Main Hatchways
		Hatches <i>good</i>

General Observations and Opinion,

This vessel is eligible in my opinion to remain as classed 14 A 1

Jos. W. Mawson

The Amount of Entry Fee.....£ : : is received by me,

Special..... 1 : 1 : *2/6/71*

Certificate (if required) : 5 :

Committee's Minute *6th June* 18 *71*

Character assigned *14 A 1*
record



© 2021

Lloyd's Register Foundation

CON656-0402